# Joining Plate – T Connection

This bracket is a steel plate to add extra stiffness to T joints. You need 5 sets of M8x12 bolts with nuts and washers. Compatible with PG40 extrusions.

**Product Specifications**

| | |
|---|---|
| **Look-up Reference** | |
| Catalogue Page | 87 |
| Manufacturer Part Number | 3.53.40.4040.02 |
| **Physical Properties** | |
| T-Slot Profile Size | PG40 |