

# Joining Plate – T Connection



This bracket is a steel plate to add extra stiffness to T joints. You need 5 sets of M8x12 bolts with nuts and washers. Compatible with PG40 extrusions.

## **Product Specifications**

### **Look-up Reference**

Catalogue Page 87  
Manufacturer Part Number 3.53.40.4040.02

### **Physical Properties**

T-Slot Profile Size PG40