

Joining Plate – T Connection



This bracket is a steel plate to add extra stiffness to T joints. You need 5 sets of M8x12 bolts with nuts and washers. Compatible with PG40 extrusions.

Product Specifications

Look-up Reference

Catalogue Page 87

Manufacturer Part Number 3.53.40.4040.02

Physical Properties

T-Slot Profile Size PG40